



---

**Release Notes for SKC300S37A, Firmware Rev. 507KC4 (05/21/13)**

- Resolved a unique incorrect value bug affecting SMART attribute 231
- Improved platform compatibility when using Secure Erase command
- Enhanced overall system compatibility